



## **East Toba River and Montrose Creek Hydroelectric Project Independent Environmental Monitor's Report**

### **Powell River Transmission Line Weekly Report for Period May 8 to May14, 2010**

**Weather:** May 8 – sunny  
May 9 – sunny  
May 10 – sunny  
May 11 – sunny  
May 12 – sunny  
May 13 – sunny  
May 14 – sunny

**Fisheries observations:** None.

**Wildlife observations:** None

**Action Items:**

### **Independent Environmental Monitor Activities**

IEM consulted with Kiewit about deactivation activities.

**Construction activities:**

#### **PKS**

Final Owner walk through inspecting the Transmission line continuing.  
Deactivation road inspection by PKS staff and contracted forester - Upper Eldred and Goat II (Access spurs)  
Grass seeding in the Upper Freda  
Final Sallery Bay substation DC battery test.

**Non-compliance activities and mitigation measures:** None.

**Action Items:**

<b>Date</b>	<b>Item number</b>	<b>Location</b>	<b>Description</b>	<b>Mitigation measures</b>	<b>Risk/priority</b>	<b>Status</b>	<b>Date completed, photo #</b>
December 18, 2009		Third Lake Sector	Provide geo technical assessment for work required at site 132/8 and carry out work identified		High	ASAP	Site assessment completed, awaiting report
February 24 2010		All sectors	End haul all damaged culverts removed as part of the final deactivation		Low	Ongoing	

**Fisheries sensitive activities and mitigations:** None.

**Sampling results:** None.