



**East Toba River and Montrose Creek Hydroelectric Project Independent Environmental Monitor's Report**

**Powell River Transmission Line Weekly Report for Period May 29 to June 4, 2010**

**Weather:** May 29 – overcast  
 May 30 – rain  
 May 31 – fog, rain  
 June 1 – overcast  
 June 2 – partial sun  
 June 3 – overcast  
 June 4 – rain

**Fisheries observations:** None.

**Wildlife observations:** None

**Action Items:**

**Independent Environmental Monitor Activities**

IEM maintained liaison with Kiewit to monitor field activities.

IEM checked conditions at the Saltery Bay sub-station and the Saltery Main.

**Construction activities:**

**PKS**

Kiewit staff doing cleanup at the Lang Bay yard.

**Non-compliance activities and mitigation measures:** None.

**Action Items:**

Date	Item number	Location	Description	Mitigation measures	Risk/priority	Status	Date completed, photo #
December 18, 2009		Third Lake	Provide geo		High	ASAP	Site assessment

		Sector	technical assessment for work required at site 132/8 and carry out work identified				completed, awaiting report
February 24 2010		All sectors	End haul all damaged culverts removed as part of the final deactivation		Low	Ongoing	

**Fisheries sensitive activities and mitigations:** None.

**Sampling results:** None.